



# RealSense™ Product Family

## D500 Series

Specification Update

Revision 002

November 2025

RealSense™ and the RealSense™ logo are trademarks of RealSense, Inc. in the U.S. and/or other countries. Other names and brands may be the trademarks or registered trademarks of third parties. INTEL® REALSENSE™, INTEL® and the INTEL® Logo are trademarks of Intel Corporation or its subsidiaries used under license. Certain Intel® RealSense™ products are sold by RealSense, Inc. under license from Intel Corporation.

# Contents

---

<b>1</b>	<b>Preface .....</b>	<b>5</b>
	1.1 Terminology.....	5
<b>2</b>	<b>Summary Table of Changes .....</b>	<b>6</b>
	2.1 Codes Used in Summary Tables .....	6
<b>3</b>	<b>Errata .....</b>	<b>7</b>
	3.1 Open.....	7
	3.2 Fixed.....	8
<b>4</b>	<b>Appendix .....</b>	<b>9</b>
	4.1 External HW Sync.....	9

## Table

Table 2-1. Errata Summary Table .....	6
Table 2-2. Specification Updates .....	6

# Revision History

---

Revision Number	Description	Revision Date	Comment
001	Firmware 7.56.19918.835 Release	May 2025	First D555 FW
002	Firmware 7.56.19919.4144 Release	November 2025	Hot fix

§§

# 1 Preface

---

This document lists the firmware versions supporting the RealSense™ Product family D500 Series.

## 1.1 Terminology

**Errata** are design defects or errors. These may cause behavior to deviate from published specifications.

**Specification Changes** are new or modified specifications introduced in published firmware versions.

§§

## 2 Summary Table of Changes

The following tables indicate the errata and specification changes which apply to the RealSense Products may fix some of the errata in a future release of the component and account for the other outstanding issues through documentation or specification changes as noted.

### 2.1 Codes Used in Summary Tables

#### Status

Open:	In engineering assessment
Fixed:	This erratum has been previously fixed
No Fix:	There are no plans to fix this erratum

Table 2-1. Errata Summary Table

Number	Status	Errata
	Open	USB is supported for debug and production line or HW Sync.
RSDEV-2744	Open	External HW Sync is supported on HW, SW support is missing. Refer to Appendix
RSDEV-3192	Open	Calibration Data is missing from Viewer
RSDEV-3293	Open	RGB-Depth UV mapping impact by thermal loop
RSDEV-3188	Open	~0.5pixel UV movement to the right for both X and Y axis
RSDEV-4775	Fixed in 7.56.19919.4144	D555: cannot be detected after changing the link-timeout setting

Table 2-2. Specification Updates

Number	Specification Changes
Firmware 7.56.19918.835	First FW version supporting RealSense™ camera D555. Note, this FW is installed in the camera and cannot be downloaded.

§§

## 3 Errata

---

### 3.1 Open

<b>RSDEV-3192</b>	<b>Calibration Data is missing from Viewer</b>
<b>Problem:</b>	The Viewer is missing the display and restore calibration data for D555
<b>Implication:</b>	Cannot restore calibration data to default
<b>Workaround:</b>	Contact customer support if needed to enable via command line, or wait for the next release
<b>Status:</b>	Refer the <i>Summary Tables of Changes</i>

<b>RSDEV-3293</b>	<b>RGB-Depth UV mapping impact by thermal loop</b>
<b>Problem:</b>	RGB-Depth UV mapping pixel error is higher when Thermal Loop (TL) is enabled
<b>Implication:</b>	UV mapping between RGB and depth is less accurate
<b>Workaround:</b>	Disable TL, which affects the Z-accuracy at high ambient temperature
<b>Status:</b>	Refer the <i>Summary Tables of Changes</i>

<b>RSDEV-3188</b>	<b>~0.5pixel UV movement to the right for both X and Y axis</b>
<b>Problem:</b>	The calibration conventions in D555 differs from D4xx. In D4xx devices the origin of the pixel is the upper left corner, while in D555 it is the center of the pixel.
<b>Implication:</b>	Texture map misalignment by 0.5 pixel horizontally and vertically in registered depth and texture PointCloud scenarios
<b>Workaround:</b>	None. Users can use external tools/libraries for Texture Mapping
<b>Status:</b>	Refer the <i>Summary Tables of Changes</i>

<b>RSDEV-3188</b>	<b>~0.5pixel UV movement to the right for both X and Y axis</b>
<b>Problem:</b>	The calibration conventions in D555 differs from D4xx. In D4xx devices the origin of the pixel is the upper left corner, while in D555 it is the center of the pixel.
<b>Implication:</b>	Texture map misalignment by 0.5 pixel horizontally and vertically in registered depth and texture PointCloud scenarios
<b>Workaround:</b>	None. Users can use external tools/libraries for Texture Mapping
<b>Status:</b>	Refer the <i>Summary Tables of Changes</i>


## 3.2 Fixed

<b>RSDEV-4775</b>	<b>D555: cannot be detected after changing the link-timeout setting</b>
<b>Problem:</b>	D555: After modifying the link-timeout parameter, D555 camera cannot be detected anymore by the SDK/Viewer.
<b>Implication:</b>	D555 camera is not detected
<b>Status:</b>	Fixed



## 4 Appendix

### 4.1 External HW Sync



- Multiple cameras can be connected to one host and will be able to stream asynchronously independent data
- The cameras can be hardware synchronized (HW sync) so they capture at exactly the same time and rate
- The host will be the synchronization master, and the cameras will be working in slave mode
- An SDK API will be used to configure the cameras in slave mode
- The main difference between the D400 (Vision Processor V1 and V3) HW sync and D555:
- D400 cameras HW sync use the 9pin aux connector—pins 5 (SYNC) and pins 9 (Ground)
- D555 will use the USB type C connector 2 SB (sideband) pins, requiring connecting a USB type C connector on the host side as well
- Note: The RGB color sensor is synchronized with the depth sensors (left and right) when they stream at the same FPS